




## SAFETY CERTIFICATE

The building of I B DAV Public School Narwana Yol Cantt. in Tehsil Dharmshala, Distt. Kangra H.P. was inspected by the concerned Junior Engineer. As per the report of Junior Engineer only the ground floor of the building is the part of school which has neither been designed nor been constructed by this office. No earthquake resistant norms have been adopted for this building. No structural drawings approved by the competent Govt. agency have been produced. The structure is a Non-Engineered Structure. Hence the structural safety of this building cannot be ensured specifically from earthquake point of view. This department will not be responsible for any type of loss of life and property etc. if this structure fails under any circumstances. However as per visual inspection the building seems to be safe at present only. This certificate is valid for academic session for 2021-22.

  
Junior Engineer  
HP.PWD Sub Division .II  
Dharmshala .

  
Assistant Engineer,  
HPPWD Sub Division. II  
Dharmshala.


  
Executive Engineer  
Dharmshala Division  
HPPWD Dharmshala


Place: Dharamshala  
Dated:

Himachal Pradesh  
Public Works Department  
No. PW/DD/CB/WAB/B-17/2021 8576-77 Dated:- 16-2-2021

✓ Copy forwarded to the Principal, DAV Sr. Sec. School Narwana, Yol Cantt., Tehsil Dharamshala, Distt. Kangra (H.P.) for information with reference to his application No. DAV/NAR/2021 dated 29-01-2021 please.

Copy forwarded to the Assistant Engineer, Dharamshala Sub-Division-II, HPPWD, Dharamshala for information with reference to his office letter No. 8428 dated 11-02-2021.

  
Executive Engineer,  
Dharamshala Division,  
HPPWD, Dharamshala

  
Principal  
D. A. V. Sr. Sec. Sch  
Narwana, Yol (H.P.)